

# MIXING SYSTEM

SERIAL:

MODEL:

Kemtron 500T Targo

ENGINE

John Deere

NOTES

(Higher Numbers are Better)

1 2 3 4 5 N/A

Fluid level and condition ☐ 1/4 ☐ 1/2 ☐ 3/4 ☒ Full

Engine Noise ☐ YES ☒ NO ☐

Engine Smoke ☐ YES ☒ NO ☐

Visible Leaks ☐ YES ☒ NO ☐

Idle and Throttle Quality ☐ ☐ ☐ ☐ ☒ ☐

Engine Mounts ☒ YES ☐ NO ☐

Any Missing Parts ☐ YES ☒ NO

## TANK

(Higher Numbers are Better)

1 2 3 4 5 N/A

Condition of Tank ☐ ☐ ☐ ☒ ☐ ☐

Hoses ☐ ☐ ☐ ☒ ☐ ☐

Caps ☐ ☐ ☐ ☐ ☒ ☐

Ball Valves ☐ ☐ ☐ ☐ ☒ ☐

Hopper ☐ ☐ ☐ ☒ ☐ ☐

Any Missing Parts ☐ YES ☒ NO

## PUMP

(Higher Numbers are Better)

1 2 3 4 5 N/A

Condition of Pump ☐ ☐ ☐ ☒ ☐ ☐

Pump Noise ☐ YES ☒ NO ☐

Visible Leaks ☐ YES ☒ NO ☐

Packings ☐ ☐ ☐ ☐ ☒ ☐

Any Missing Parts ☐ YES ☒ NO

## TRUCK

SERIAL:

MODEL:

MILAGE:

(Higher Numbers are Better)

1 2 3 4 5 N/A

Cab and Body ☐ ☐ ☐ ☐ ☐ ☒

Paint ☐ ☐ ☐ ☐ ☐ ☒

Panel Dents ☐ YES ☐ NO ☒

Rust ☐ YES ☐ NO ☒

Any Missing Parts ☐ YES ☐ NO

## TRAILER

SERIAL:

MODEL:

(Higher Numbers are Better)

1 2 3 4 5 N/A

Paint / Rust ☒ YES ☒ NO ☐

Damage ☐ ☐ ☐ ☒ ☐ ☐

Tires ☐ ☐ ☐ ☐ ☐ ☐

Lights ☒ YES ☐ NO ☐

Brakes ☐ ☐ ☐ ☐ ☒ ☐

12) ST235/80R16 90% Tread

This inspection report has been furnished solely for informational purposes and it is not to be construed in any way as a warranty or guarantee on the condition of the equipment. Buyers should confirm the accuracy of this report to their satisfaction prior to purchase. Buyer agrees to hold harmless HDD Broker, the seller and the inspecting agent.